San Diego – Southwest Blackout September 8, 2011



Dan Head Consolidated Edison of NY, Inc. System Operations (Operations Analysis Group)



Agenda

- System Overview
- Voltage Angle & Power Transfer
- System Conditions
- Sequence of Events
- Frequency
- Impacts
- Recommendations
- Questions



System Overview: San Diego





System Overview: Affected Area





System Overview: Balancing Authorities

5 of 37 total in the Western Electricity Coordinating Council (WECC)



ConEdison





Parallel Paths

Western Interconnection





Voltage Angle & Power Transfer Two Systems as Synchronous Machines



Depiction of Two Systems as Rotating Synchronous Machines



Voltage Angle & Power Transfer Power Transfer Equation





Voltage Angle & Power Transfer Two Parallel Lines





ON IT

System Conditions

Good weather, but warm

- 86 degrees Fahrenheit in San Diego (vs. 77 normal)
- 113 degrees in Yuma, Arizona (vs. 104 normal)
- Loads in the range of <u>90 to 95 percent of summer peak</u>
- San Diego load running <u>6% above the day-ahead forecast</u>
- Thursday after Labor Day
 - "Shoulder" season for maintenance outages had begun
 - Mid afternoon
- Heavy imports
 - San Diego importing almost half its load level of 4,300 MW
 - Impacted area importing about <u>one third of its load level of 7,900 MW</u>



System Conditions: Critical Issues

SONGS Separation scheme not monitored

 WECC and California ISO <u>unaware</u> of automatic separation scheme between Southern Cal Edison and San Diego Gas & Electric

Outages in neighboring areas not taken into consideration

 Maintenance outage on a 600 MW generator in Mexico <u>not included</u> in dayahead plan of Imperial Irrigation District (IID)

Contingency Alarm Missed

- 44 minutes prior to the initiating event, IID's real-time contingency analysis showed the loss of one 230/92 kV transformer would overload another beyond its trip point
- <u>Operator was not monitoring the contingency analysis</u>

Phase imbalance relay operation on series capacitor

 2-1/2 hours prior to the initiating event, the series capacitor on a 500 kV line in Arizona was automatically by-passed



System Conditions: One-Line Diagram & Flows





Sequence of Events Series Capacitors at North Gila Station





Sequence of Events Disconnect Switch





Sequence of Events: Line Trips





Sequence of Events: Cascading Outages





Sequence of Events: Separation & Collapse





Sequence of Events: Path 44 Current





Frequency: One-Second Resolution (WECC)





Frequency: Underfrequency Load Shedding

Figure 14: Actual and Simulated Frequency at Miguel 500 kV Bus





Effects: Key Statistics

- 2.7 million customers interrupted
 - Population of roughly 6.9 million
 - Land area of roughly 38,000 square miles (size of Indiana)
- 7,890 MW of firm load interrupted
- 6,981 MW of generation forced off-line
- No equipment damage reported
- 12 hours to restore all load
 - Load restoration proceeded smoothly
- 87 hours to restore all generation
 - 39 hours, not counting the San Onofre nuclear facility



Impacts: San Diego





FERC/NERC Findings & Recommendations

Twenty-seven in all. The following were highlighted:

- Failure to update external networks in next-day study models (# 2)
- Lack of real-time external visibility into neighboring systems (# 11)
- Impact of sub-100 kV facilities on bulk power system reliability (# 3, 6, & 17)
- Failure to recognize Interconnection Reliability Operating Limits – IROLs (# 18)
 - WECC claimed that these didn't exist within WECC because, if all entities observed their respective System Operating Limits (SOLs), no contingencies would lead to cascading. The September 8 event disproved this claim.

 # 19 – 23: Failure to study and coordinate special protection systems (# 19 – 23)



Wellinghoff & Cauley News Release

- <u>Overload Protection</u>: Relay settings should not encroach on emergency ratings or, if they do, the emergency ratings should be lowered accordingly.
- <u>Phase Angle Difference</u>: The 500 kV Hassayampa North Gila line couldn't be restored even though the fault was cleared because the angular separation across its open breaker exceeded the synchronism check setting of 60 degrees.
 - Operators weren't aware of this condition.
 - Tools, such as Phasor Measuring Units (PMUs) can provide the necessary information to Operators.



Questions



