Request from NYPA to expedite RRS review of NYPA's proposed modification of NYSRC Exception No. 12

Background:

During the refurbishment of the Marcy Westinghouse AT-2 transformer the Marcy AT-1 ASEA spare phase will be placed in service in the AT-2 transformer. During that time the existing Marcy AT-2 overload protection scheme must be enabled.

NYPA requests the NYSRC EC expedite RRS review of the proposed changes to Exception No. 12 as outlined below:

Exception Reference No.	то	Exception Category	Exception	NYSRC Reliability Rule
12	NYPA	Monitoring & Special Protection System	Post Contingency Flow on Marcy AT-2 Transformer The post-contingency flow on Marcy AT-2 transformer The bank is allowed to exceed its LTE rating up to its STE rating following the loss of Marcy AT-1 Transformer. When the AT-1 ASEA spare phase transformer is substituted in the Marcy AT-2 Westinghouse transformer bank, the post-contingency flow on the Marcy AT-2 bank is allowed to exceed its STE rating for the loss of Marcy AT-1 Transformer bank, provided that the overload relay protection on the AT-2 bank is in-service.	B.1 and C.1*