

NYISO Self-Certification

Description:

NYSRC Reliability Rule Reference (No. and Name)

C.3: Outage Coordination

NYSRC Requirement(s) for which compliance is being self-certified

R6. The *NYISO* shall maintain procedures and systems which ensure that outages of transmission facilities are coordinated in such a manner to ensure *reliability*. The *NYISO* must notify the *NYSRC* of any changes to these procedures and systems.

Compliance Monitoring Process

Compliance Monitoring Responsibility:

- **M1:** RCMS

Compliance Documentation Reporting Frequency:

- **M1:** In accordance with *NYSRC* Compliance Monitoring Program schedules.

Compliance Reporting Requirements:

- **M1:** Self-Certification

Measure No.

<input checked="" type="checkbox"/> Full Compliance	M2. The <i>NYISO</i> certified that each Transmission Owner maintained transmission outage coordination procedures and systems in accordance with R6. Any material revisions to these procedures and systems were reported to the <i>NYISO</i> .
---	---

Levels of Non-Compliance

<input type="checkbox"/> Level 1	M1. Revisions to existing procedures or systems were not reported to the <i>NYSRC</i> .
<input type="checkbox"/> Level 2	M1. <i>NYISO</i> procedures and systems for coordination of transmission facility outages were incomplete in one or more areas.
<input type="checkbox"/> Level 3	M1. Not applicable.
<input type="checkbox"/> Level 4	M1. <i>NYISO</i> procedures and systems for coordination of transmission facility outages were not provided.

Notes: The NYISO maintains procedures and systems which ensure that outages of transmission facilities are coordinated in such a manner to ensure reliability as per the Outage Scheduling Manual Sections 2.2, 2.3, and 4.

Certified by: W. Bennett

Title: Supervisor, Scheduling

Date: June 03, 2021