NYISO Self-Certification

Description:

NYSRC Reliability Rule Reference (No. and Name)

C.3: Outage Coordination

NYSRC Requirement(s) for which compliance is being self-certified

R6. The *NYISO* shall maintain procedures and systems which ensure that outages of transmission facilities are coordinated in such a manner to ensure *reliability*. The *NYISO* must notify the *NYSRC* of any changes to these procedures and systems.

Compliance Monitoring Process

Compliance Monitoring Responsibility:

M1: RCMS

Compliance Documentation Reporting Frequency:

• M1: In accordance with NYSRC Compliance Monitoring Program schedules.

Compliance Reporting Requirements:

• M1: Self-Certification

Measure No.

<u>X</u> Full	M1. The NYISO maintained transmission outage coordination procedures and
Compliance	systems in accordance with R1 to R6. Any revisions to these procedures
	and systems were reported to the NYSRC.

Levels of Non-Compliance

Level 1	M1. Revisions to existing procedures or systems were not reported to the NYSRC.
Level 2	M1. NYISO procedures and systems for coordination of transmission facility outages were incomplete in one or more areas.
Level 3	M1. Not applicable.

Level 4	M1. NYISO procedures and systems for coordination of transmission facility outages were not provided.

Notes:

The NYISO maintains procedures and systems which ensure that outages of transmission facilities are coordinated in such a manner to ensure reliability as per the Outage Scheduling Manual Sections 2.2, 2.3, and 4.

Certified by: A. Markham

Title: Manager, Grid Operations

Date: April 28, 2016