



The results presented today are not final. During the process of conducting the Tan45 analysis, the LOLE in ISO-NE fell slightly below 0.1. Policy 5 directs ISO-NE to be postured at an LOLE greater than or equal to 0.1 LOLE. The NYISO believes adjusting ISO-NE to 0.1 LOLE should produce a minimal change in the IRM. The NYISO is in the process of adjusting the ISO-NE LOLE to meet Policy 5 and will post the results of the updated Tan45 when they become available.