## **NYISO Self-Certification**

## **Description:**

## **NYSRC Reliability Rule Reference (No. and Name)**

### C.5: Fault Current Assessment

## NYSRC Requirement(s) for which compliance is being self-certified

- **R1.** The *NYISO* shall perform pre-seasonal assessments, and additional re-evaluations if required by system changes, to evaluate *fault* duty at each *NYS Bulk Power System* station. The *NYISO* shall notify the applicable equipment owner and other potentially affected *Market Participants* of any location expected to exceed equipment *ratings*.
- **R3.** After the equipment owner has reported its findings on the *NYISO's* assessment (as required by R2), the *NYISO*, in consultation with the equipment owner and the other potentially affected *Market Participants*, shall develop, if necessary, an appropriate mitigation plan.

## **Compliance Monitoring Process**

#### **Compliance Monitoring Responsibility:**

M1: RCMS

### **Compliance Documentation Reporting Frequency:**

• **M1**: Annually

#### **Compliance Reporting Requirements:**

• M1: In accordance with Annual Compliance Monitoring Program requirements

#### Measure No.

X Full Compliance	<b>M1.</b> The <i>NYISO</i> (a) performed <i>fault</i> duty assessments, and (b)
	developed mitigation plans, if necessary, in accordance with R1 and R3.
	Documentation of these assessments and mitigation plans were
	reported to the NYSRC as requested.

# **Levels of Non-Compliance**

Level 1	M1. Not applicable.
Level 2	M1. Not applicable.
Level 3	<b>M1</b> . The required fault duty assessment was completed, but the NYISO failed
	to notify breaker owners of pending conditions whereby fault duty levels may

	exceed appropriate <i>ratings</i> in sufficient time to permit the condition from being prevented.
Level 4	<b>M1.</b> The required <i>fault</i> duty assessment was not completed; or the <i>fault</i> duty assessment was completed, but the <i>NYISO</i> failed to develop the required mitigation plan.

**R.1 & R.3** 2020 NYISO Fault Current Assessment performed according to the NYISO Guideline for Fault Current Assessment and were reviewed and approved by the NYISO Operating Committee on May 21, 2020. As a mitigation measure for certain fault current conditions identified in sensitivity analysis the Operating Protocol for Astoria East and West Stations Fault Current Mitigation, approved by the Operating Committee on Feb 13, 2020, will continue to be implemented. Of the stations evaluated, there are no over-dutied breakers.

**Certified by:** P. Nirbhavane

Title: Supervisor, System Modeling

**Date:** June 25, 2020